RECEIVING INSPECTION REPORT
HYCON MFG. COMPANY
961 E. COLORADO ST. PASADENA, CALIF.

No. 11814

RECEIVED FROM										DATE REC'D		
										P.O. NO.		
		PLANT #9								VENDOR PACKING SLIP NO.		
	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	O R	ACCT. OR W.O. NO.		
CHARGE TO	327		-7	0	10					B.O. NO.		

QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION	QUANTITY		REMARKS
		ACCEPTED	REJECTED	
27	731342 Spacers	27		
	IPS #05308			

RECEIVED BY _____   INSPECTED BY _____   DATE 11-5-57   REJECTS RETURNED ON SUPPL. MEMO NO.

RECEIVING INSPECTION REPORT
HYCON MFG. COMPANY
961 E. COLORADO ST. PASADENA, CALIF.

No. 11813

RECEIVED FROM										DATE REC'D		
										P.O. NO.		
		PLANT #9								VENDOR PACKING SLIP NO.		
	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	O R	ACCT. OR W.O. NO.		
CHARGE TO	32		300	0	13					S.O. NO.		

QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION	QUANTITY		REMARKS
		ACCEPTED	REJECTED	
26	731908-A Spacer IPC Mount	26		Stores
	IPS #00438			
	To supersede Rec. Insp. Report #11779 dated 4-3-57			

RECEIVED BY _____   BY _____   DATE _____